Peachland Creek

Current Condition Map

Date: 3/22/2018

- Operating Areas
- H40 Snow Sensitive Line
- Watershed
- Basin
- Hydrometric Station
- Field Stop Locations
- Community Water Intake
- Points of Diversion
- Highway
- FTEN (Active) Roads
- Planned Roads
- Streams
- Lakes
- Wetland
- Woodlot
- Stand Percentage Dead > 30
- Approved Blocks
- 2025 Planned Harvest
- 2020 Planned Harvest
- 2018 Planned Harvest
- Parks
- Private Land

Contours

- 100m
- 20m

Current Recovery

- N/A
- 75 - 99.9 %
- 50 - 75 %
- 25 - 50 %
- 10 - 25 %
- 0 - 10 %

Surface Erosion Potential

- Very High
- High
- Moderate

N

1:25,000

Kilometers

0 0.75 1.5 3

Coordinate System: NAD 1983 BC Environment Albers
Projection: Albers
Datum: North American 1983
False Easting: 1,000,000.0000
False Northing: 0.0000
Central Meridian: -126.0000
Standard Parallel 1: 50.0000
Standard Parallel 2: 58.5000
Latitude Of Origin: 45.0000
Units: Meter

FORSITE
Forest Management Specialists

Westbank First Nation
Tolko Industries Ltd.
Upper Peachland Creek
Mid Peachland Creek
Peachland Lake
Brenda Lake
George Lake
Long Lake
Headwater Lakes
Crescent Lake
Chapman Lake
Glen Lake
Eneas Lakes
Tsuh Lake
Silver Lake
Spring Lake
Okanagan Lake
Lake/Park
Residual Above Intake
District of Peachland Community Water Intake
GREATA CREEK NEAR THE MOUTH (DNAUP)
German Bros. Lumber Ltd.